

**DEPARTMENT OF TRANSPORTATION****DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021348**Date Inspected:** 07-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr.Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

BAY # 14

This QA Inspector randomly observed the following work in progress.

OBG 14EAST

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 215553 performing the Shielded Metal Arc Welding process on weld 037 located at PCMK SEG3019BB. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical weld repair report identified as B-CWR2737.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066422 performing the Shielded Metal Arc Welding process on weld 059 located at PCMK SEG3019BB. ZPMC QC Mr. Guo Xing Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-Fcm-Repair-1. Critical weld repair report identified as B-CWR2737.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066236 performing the Flux Cored Arc Welding process on weld 003 located at PCMK SEG3019U. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067817 performing the Flux Cored Arc Welding process on weld 009 located at PCMK SEG3019Z. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066763 performing the Flux Cored Arc Welding process on weld 003 located at PCMK SEG3019BB. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067079 performing the Flux Cored Arc Welding process on weld 157 located at PCMK SEG3019BB. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 068501 performing the Flux Cored Arc Welding process on weld 131 located at PCMK SEG3019AZ. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066733 performing the Flux Cored Arc Welding process on weld 165 located at PCMK SEG3019AZ. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 068097 performing the Shielded Metal Arc Welding process on weld 156 located at PCMK SEG3019J. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2213-Tc-u4b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 044772 performing the Shielded Metal Arc Welding process on weld 131 located at PCMK SEG3019J. ZPMC QC Mr. Xie Ming Feng was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-P-2213-Tc-u4b-Fcm-1.

This Quality Assurance (QA) Inspector observed ZPMC personnel performing heat straightening, member identified as bottom panel (BP3079) and longitudinal diaphragm (LD3040). Distortion appeared to be caused by welding. ZPMC Quality Control (QC) inspector identified as Mr. Xie Ming Feng was present to monitor the heat straightening process. The heat straightening appeared to comply with heat straightening Report HSR1 (B)-09979.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

---

## WELDING INSPECTION REPORT

( Continued Page 3 of 3 )

---



### Summary of Conversations:

No significant conversations were reported on this date.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Utekar,Shrikant	Quality Assurance Inspector
<b>Reviewed By:</b>	Patterson,Rodney	QA Reviewer

---